

DESCRIPTION of Porch #1706 OGEECHIE RD.

THE original door will be replaced and the would suffice the opening SEEN ON photos. THE previous OWNER tried one installed a door but isn't the original door. By installing wrong door it left gaps and missing PANELS do to improper door. (As you see green foam on house outside) THE original door is much wider and has windows attached to original door on each side. \* THE

Porch - will be installed or REPAIRED BACK to the original design. sketch of Porch inclosed.

1706 OGEE CHEE RD.

Siding: My Plan to remove old siding / or replace siding.


I will be using  $3\frac{1}{2}$  original siding like on photos in picture.

Siding will come from / came from Guerry Lumber Treated wood.




Add

will COVER  
empty SPACE  
GLASS  
door



Add

will COVER  
empty SPACE  
GLASS  
door













**seal**

**WATER-RESISTIVE & AIR BARRIER PROTECTION**

**7/16" STRUCTURAL PANEL**

07-14-ZS 19:21 CSD R