

The metal roof over the former loading dock at the back of the building was installed without a COA by the previous tenant. It was brought to my attention by code compliance. As the owner and a general contractor, we are working towards getting this in compliance.

The roof is wood framed with a v-grove metal surface.

Thanks,

Wells Anderson

5



6



3' 1\"/>

11' 5\"/>

16'



②



