

Penelope Combs
514 E Duffy St
Fence Rehabilitation

Written project description:

Demo the existing chain link on the property and replace with a rehabilitated wood fence.

Clear color photographs of the area proposed to be fenced:



Backyard of home taken from the rear of the house facing away. Chain link fence in the back and along the right-hand side.




My house is on the left side; neighbor's house is on the right side. Dilapidated wood fence in between the neighbors overflowing trash to be replaced.



My house is on the right. Chain link fence to be replaced on the left.

Site Plan:

Provided by the contractor to do the work. North is to the right, E Duffy St is to the left, and E Park Ln to the right.



Fence Elevation: 6'

Material: Pressure treated wood

