

211 West Henry Street

Scope of work:

Siding Repairs & Exterior Painting (Left & Right Side Only)

Pressure wash (soft wash) all exterior surfaces of the house using a solution of water, and bleach to remove mildew and mildew spores.

Remove and replace the rotten pieces of siding on the left and right side of the house with NEW #119 1x6x16 Pine Lap Siding (approximately 700 linear ft).

Remove and replace the rotten 1x6 vertical trim board on (6) of the windows and repair (2) rotten windows sills.

Scrape and/or light sand any cracking/peeling areas and caulk all open cracks and joints with siliconized acrylic caulk.

Apply (1) Coat Tinted Oil based primer to all exterior wood surfaces.

Apply (2) Coats Sherwin Williams Superpaint to all exterior wood surfaces of the house.












































211

Manufacturers Specifications:
Bondo Wood Filler
#119 1x6 Pine Lap Siding
1x6 Common Board (window trim)
Sherwin Williams SuperPaint

Physical samples of proposed materials:



Bondo Wood Filler



#119 1x6 Pine Lap Siding



1x6 Common Board (window trim)



Sherwin Williams SuperPaint