



Comment of the Oglethorpe Plan Coalition, Inc. on 114 West Bay Street, The Jones-Telfair Range


HISTORIC (WEST SIDE)



SIX-OVER-NINE DOUBLE-
HUNG SASH WINDOW
(1850s)




HISTORIC (EAST SIDE)



TWO-OVER-FOUR
DOUBLE-HUNG SASH
WINDOW
(ca. 1880s)

HISTORIC (EAST SIDE)




TWO-OVER-FOUR
DOUBLE-HUNG
SASH WINDOW

PROPOSED (EAST SIDE)



- Reversed: Four Over Two
- Not Recessed Sufficiently
- Sash (Muntin) Rail Too Thick


HISTORIC (WEST SIDE)



SIX-OVER-NINE DOUBLE-
HUNG SASH WINDOW



EXISTING (WEST SIDE)



- No Relationship to the Historic Windows:
Thick Sash Rail, Four-Over-Eight
- Master Plan for Proper Window Replacement
Should Be Established